

**ROCKY FLATS PLANT  
EMD OPERATING  
PROCEDURES MANUAL**

Manual No.: 5-21000-OPS-AP  
Procedure No.: Table of Contents, Rev 2  
Page: 1 of 2  
Effective Date: 1/28/92  
Organization: Environmental Management

**THIS IS ONE VOLUME OF A SIX VOLUME SET WHICH INCLUDES:**

**VOLUME I: FIELD OPERATIONS (FO)**

**VOLUME II: GROUNDWATER (GW)**

**This is a VOLUME III: GEOTECHNICAL (GT)**

**CONTROLLED DOCUMENT VOLUME IV: SURFACE WATER (SW)**

**EG&G — ROCKY FLATS PLANT**

**ENVIRONMENTAL MANAGEMENT DEPARTMENT**

**VOLUME V: ECOLOGY (EE)**

**VOLUME VI: AIR (AP)**

**This is a KEY DOCUMENT**

**TABLE OF CONTENTS  
FOR VOLUME VI: AIR**

<b>Procedure No.</b>	<b>Title</b>	<b>Rev. No.</b>	<b>Effective Date</b>
AP.01	Effluent Tritium Sample Collection	0	10/04/91
DCN 91.01	Seal inspection requirement	0	11/08/91
DCN 92.01	Caution on seals	0	01/28/92
AP.02	Tritium Sampler Calibration	0	10/04/91
DCN 91.01	Seal inspection requirement	0	11/08/91
DCN 92.01	Caution on seals	0	01/28/92
AP.03	Effluent Air Radioparticulate		
AP.04	Effluent Air Radioparticulate Sample Calibration		
AP.06	Effluent Air Pitot Tube Inspection and Replacement		
AP.08	Volumetric TSP/PM <sub>10</sub> Calibration , Ambient Air Particulate Sampling High Volume Method	0	10/01/91
AP.09	Ambient TSP/PM <sub>10</sub> Air Particulate Sampling High Volume Method	0	10/01/91

**ADMIN RECORD**

A-SW-001045

**REVIEWED FOR CLASSIFICATION/UCNI**  
By J. F. JENCHURA UNO  
Date 1/28/92

**ROCKY FLATS PLANT  
EMD OPERATING  
PROCEDURES MANUAL**

**Manual No.: 5-21000-OPS-AP  
Procedure No.: Table of Contents, Rev 2  
Page: 2 of 2  
Effective Date: 1/28/92  
Organization: Environmental Management**

<b><u>Procedure No.</u></b>	<b><u>Title</u></b>	<b><u>Rev. No.</u></b>	<b><u>Effective Date</u></b>
AP.10	Radioactive Ambient Air Monitoring Particulate Sampling Data Reduction	0	10/01/91
AP.11	Mass Flow TSP/PM <sub>10</sub> Calibration, Ambient Air Particulate Sampling High Volume Method	0	10/01/91
AP.12	Placement, Design, Installation, and Operation of Meteorological Monitoring Stations		
AP.13	Radioactive Ambient Air Monitoring Program	0	10/01/91
AP.14	Meteorology Data Downloading		
AP.15	Restoration Projects Data Reduction for Radioactive Ambient Air Monitoring	0	10/01/91
AP.16	Restoration Projects Radioactive Ambient Air Particulate Sampling High Volume Method	0	10/01/91
AP.17	Sampling Procedure, Volatile Organic Compounds Method TO-14	0	10/01/91
AP.18	Sampling For Organochlorine Pesticides and Polychlorinated Biphenyls in Ambient Air (SVOD)	0	10/01/91
AP.19	VOC Sampling		
AP.20	SVOC Sampling		
AP.21	Particulate Suspended Metals Sampling		

# ENVIRONMENTAL MANAGEMENT DOCUMENT CHANGE NOTICE (DCN)

Procedure Number 5-21000-OPS.

AP.02 Rev.0

Page 1 of 1

Title Tritium Sampler Calibration	Date 1/27/92	DCN Number 5-21000-OPS- AP.Z 92.01
Expires Upon Incorporation 4-31-92	Procedure Revision Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Scope Limitation <u>Name</u>	<u>1/28/92</u>	

Item Number	Page	Step or Paragraph	Changes (Use DCN CONTINUATION SHEET for Additional Space)
1	8	6.2.28	<p>Add the following sentence to step 6.2.28</p> <p>"The inspection shall include the seals, vacuum tubing, and all other parts of the equipment."</p> <p style="text-align: right;"><i>John R. Smith, QAPM</i></p> <p style="text-align: right;"><i>1/27/92</i></p>

Justification (Reason for Change – Provide Numbers To Reference Corresponding Items Above)

Inspection of the seals required to ensure equipment performance.

Concurrence	Organization	Req	Date	Concurrence	Organization	Req	Date
<u>MEG SRW</u>	QAPM	X	1/27/92	<u>M. J. Jones</u>	User	X	1-27-92
<u>JMC Brown</u>	EOM	X	1/27/92				
Approval of Responsible Manager		Date		Is Posting Req'd?	If Yes, By What Date?	Date Posted	
<u>James L. Klemm</u>		1/27/92		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	1/31/92		